

FORCE GAUGE PCE-DFG N 10K

With external measuring cell and USB interface for connection to a PC

The force gauge measures both tensile and compressive forces with a very high resolution. Tensile and compressive forces are often measured in test laboratories, for example to determine the yield strength, the pull-off force and the force required to actuate a push-button or switch. The force gauge is supplied with an external measuring cell. The PCE-DFG N 10K force

gauge can measure up to 10,000 N / 2,248 lbs. Models for 1,000 N / 225 lbs, 2,500 N / 562 lbs and 5,000 N / 1,124 lbs are also available. Various eyelets or hooks with M10 or M12 threads can be screwed into the measuring cells but other devices with the same thread can also be attached to the measuring cell.

ISO cal option

- USB interface
- memory capacity for 100 measurements
- incl. ISO calibration certificate
- graphical display
- fast response time
- PC software



APPLICATION





TECHNICAL SPECIFICATIONS

 $\begin{array}{lll} \text{Measurement range} & 0 \dots 10,000 \text{ N} / 0 \dots 2,248 \text{ lbs} \\ \text{Resolution} & 5 \text{ N} \\ \text{Accuracy} & \pm 0.1 \% \text{ of the measuring range} \\ \text{Units} & \text{N, kg, lb, KPa} \\ \text{Display} & 2.8 \text{ "TFT graphical display} \\ \text{Alarm modes} & \text{inside, outside, crack, shutdown} \\ \text{Sampling rate} & 6 \dots 1600 \text{ Hz} \\ \end{array}$

Memory 100 measurements, 8000 values each Power supply rechargeable NiMH battery, 6 V / 1600 mAh Battery life approx. 10 h Mains / charging adaptor 12 V / 1 A Outputs Interface: USB

Switching output: 12 V / 50 mA
Protection class

Operating and storage conditions

Switching output: 12 V / 50 mA
IP 54

-10 ... 50 °C / 14 ... 122 °F

5 ... 95 % RH non-condensing

Mounting thread measuring cell up to 1000 N / 225 lbs M10 2500 ... 10000 N / 562 ... 2,248 lbs M12

Dimensions 200 x 97 x 42 mm / 7.9 x 3.8 x 1.7 Weight 540 g / 1.2 lbs

Optional accessories:

Clamping device for tensile tests Order code PCE-SJJ012 PCE-SJJ09 Fork holder for tensile & compr. tests Order code PCE-SJJ06 Adaptor clamp for tensile tests Order code Round adaptor stamp for compr. tests PCE-SJJ04 Order code PCE-SJJ01 Adaptor for compr. tests Order code PCE-SJJ015 Clamping device for test stand Order code

Further models of the PCE-DFG N series:

PCE-DFG N 5 PCE-DFG N 10 PCE-DFG N 20 PCE-DFG N 500 PCE-DFG N 1K PCE-DFG N 5K PCE-DFG N 20K PCE-DFG N 50K	internal measuring internal measuring internal measuring internal measuring external measuring external measuring external measuring external measuring external measuring	cell meas. range cell meas. range	0	5 N 10 N 20 N 200 N 500 N 1000 N / 100 kg 2500 N / 250 kg 5000 N / 500 kg 20000 N / 2 t
PCE-DFG N 50K PCE-DFG N 100K	external measuring external measuring	•		50000 N / 5 t 00000 N / 10 t



Subject to change without notice