

Light Meter 100000Lux

Model: TA8120



Features:

- CE certification.
- 3-1/2 digit LCD display, Max reading 1999.
- Hand or Auto measuring range: 0~200,000Lux
- LUX/FC Unit selection
- MAX and MIN Reading Hold Function
- Storage 50 data and delay logging function (1 to 60 seconds selection)

Specifications:

Model	TA8120
LCD Display	1999
Measuring Range	2000/20000/100000 Lux 200/2000/10000 Fc
Resolution	1 Lux
Accuracy	±4% rdg ± 10dgt ($< 10,000$ lux) ±5% rdg ± 10dgt ($> 10,000$ lux) Total accuracy: for C.I.E standard illuminate A(2856K)
Repeatability	±2%
Sampling Rate	2 times/second
Range Selection	Automatic measurement / manual measurement
Data Hold	Display "H"
MAX/MIN Record	√
LUX/FC Selection	√
Data Logging	√(50 data)
Low Battery Display	√

Working Temperature	0°to 40°C (32°F to 104°F) < 70% R.H.
Deposited Temperature	-10°to 55°C (14°F to 122°F) < 70% R.H.
Power	Two AAA batteries
LCD size	35*32mm
Dimensions	185mm(L) x 55mm(W) x 30mm(H)
Weight	Approx.130g
Standard Accessories	Manual, Battery,Certificate,Bag,Box



Made in China