

NO NEED TO SET
ZERO BEFORE USE

- No need to set zero before use
- With mounting holes (for M5 screws)

Code	Length	Sensitivity
4908-100	100mm	0.1mm/m (=0.0057°)



4908-100

MINI LEVEL
←INSIZE→ PLUS
MADE IN GERMANY

Unit: mm

